



Square to right of list indicates recommended
spares advice from PML Process
(support@pmlprocess.com)

Optical Scientific, Inc.

OFS-2000W Spare Parts Pricing

Unit	Sub Assembly	P/N	
TX Head Unit	Complete TX Head Assembly	1910-100-1	
	TX LED Module	1910-110-1	
	TX Adjuster Mount (incl. LED module)	1910-111-1	
	TX Driver PCB	1910-113-2	
RX Head Unit	Complete RX Head Assembly	1910-200-1	
	RX Preamp w/ Optics Assembly & Stub	1910-210	
	RX Preamp PCB only (no optics / stub)	1910-212	
	Receiver Amplifier PCB	1910-213	
TX/RX Head	TX/RX Housing (Head w/ hinged door only)	FM-1233-01	
	TX/RX Extender Flange Mount (contin. weld)	1910-116	
	Quartz Glass Window Assy. w/ Heaters	1910-115-1	
	Sapphire Glass (HF Resist) Window w/ Htrs.	1910-115-2	
	Kevlar 4 inch Flange Gasket (min. order 2)	FS-1456-00	
	Kevlar (400F) Ring Gasket (min. order 2)	FS-1569-00	
	Graphite (850F) Ring Gasket (min. order 2)	FS-1569-01	
	Window Retaining Ring for 1 window, w/ Gaskets & Screws (6 hole / Stainless Steel)	1910-808-1	
	Sight Glass (Fused Stainless Stl.) w/ Gaskets	1910-430	
	Sight Glass (Borosil. Glass) w/ Gaskets	1910-431-0	
	Sight Glass (Hi Temp Silica) w/ Gaskets	1910-430-3	
	Silicon Flange Gasket	FS-1456-04	
	Control Box	Complete Rack Mt. Control Unit Assembly	1910-500
		Complete NEMA4 Control Unit Assembly	1910-301
Control Module (Keypad/Display)		1910-309	
Control PCB		1910-311	
4 Button Keypad		MK-1290-00	
VFD Display		ML-1291-00	
DSP PCB		1910-312	
AC Power Supply		MP-1010-00	
AC Surge Suppressor		MZ-0383-00	
4-20 ma (single) and RS-232 Interface PCB		1910-324	
DSP Firmware Update	OFSDM-x		

OSi Terms and Conditions apply

(Subject to change without notice)